















POWERPS SONIC®


SLA Batteries PS, PSG, PSH and PG Series Terminal Details

F1  FASTON 0.187" x 0.032" quick disconnect tabs.	WL INSULATED WIRE LEADS <ul style="list-style-type: none"> Molex Housing 5264-02 & 5263-PBT plug on PS-605 AMP Housing 1-480318-0 & 8116-1 on PS-1208 	NB1  Torque: 2.0~3.0 Nxm	B, T6 THREADED INSERT - 6mm STUD  Torque: 3.9~5.4 Nxm
F2  FASTON 0.250" x 0.032" quick disconnect tabs	PC PRESSURE CONTACTS	NB2  Torque: 3.9~5.4 Nxm	T8 THREADED INSERT - 6mm STUD  Torque: 3.9~5.4 Nxm
FP  FASTON POLARIZED Positive: "F2", Negative: "F1"	TH TOY BATTERY CONNECTORS H-connector PS-6120 TH	NB3  Torque: 3.9~5.4 Nxm	T11 THREADED INSERT - 8mm STUD  Torque: 11.0~14.7 Nxm
F1/O  6 4.8 21 0.6	TS TOY BATTERY CONNECTORS S-connector PS-6120 TS	NB4  Torque: 3.9~5.4 Nxm	T12 THREADED INSERT - 5mm STUD  Torque: 2.0~3.0 Nxm
SP  SPRING TERMINALS Fully collapsible positive and negative contacts	U  Positive: 17.4, 18, 22, 19 Negative: 15.9, 18, 22, 17.5 Torque: 11.0~14.7 Nxm		

POWERPS SONIC®

Terminal Illustrations 3D Perspective


F1/F2




SP




NB1/NB2




Pressure Contacts




NB3




B




T8



WL




NB4




T11/T12



U -



U +



These drawings show the terminal type only. For orientation and size details of the terminals please consult our product specification sheets.

The plug connections for PS-6120 Toy model, TH and TS, are detailed on the product specification sheet.