



Care Instructions

Washing

- **Never use chlorine bleach**
- **Wash temperature maximum 120°F with non-chlorine bleach (for home laundering)**
- Do not overload washer
- Turn garments inside out before washing
- Use high water level
- The garment can be washed up to 165°F maximum with a quality detergent (industrial laundering)
- Do not use softeners
- Do not use starch
- Do not use tallow soap, i.e. containing animal fat

Drying

- Do not use extreme heat or over dry. Maximum stack temperature 165°F (Basket temperature should not exceed 280°F industrial wash).
- Tumble dry using permanent press settings
- For best long term results: Remove garment immediately when dry or when slightly damp. Complete drying on a hanger.

Pressing

- Garments may be touched-up with an iron on permanent press settings if needed

Clean garment thoroughly. Failure to follow manufacturer's recommendations could adversely affect the flame-resistance of the fabric. Follow these procedures to maximize the life and appearance of your garment. All textile fabrics will burn and generate smoke under certain fire conditions. It is up to the ultimate users to determine if garments made from **Pyrosafe by antex**® fabrics are suitable for their needs.