

# SELF FUSING SILICONE TOOL TAPE: 10M X 25MM

PART CODE: **ST**



**HEIGHT  
SAFETY**

## PRODUCT FEATURES >

- Self fusing silicon tape for easy adhesion, no heat required.
- Hi-Vis Orange tape for easy visual location.
- Durable silicone provides long lasting adhesion and grip.

## PRODUCT DETAILS >

- **Tape Material:** Silicone
- **Weight:** 95 grams
- **Width:** 25mm
- **Length:** 10M

## TOOL LANYARD INSTRUCTIONS >

- **Tether Point:** Begin with a tether point on the tool itself. As many tools don't have an attachment point for a tool lanyard, LINQ have developed tether points that can be retrofitted to any tool without causing damage or limiting its use.
- **Tool Lanyard:** There are different types of tool lanyards for different equipment, tasks and environments. Its important to assess both your tools and where they'll be used to decide which kind of lanyard is most suitable. You may want to have several types and lengths of lanyards to allow you to use your tools in various scenarios without any difficulty.
- **Anchor Point:** The anchor point needs to be just as robust as the rest of the system. For lighter tools, they can be secured to a wristband, a workbelt or to a harness worn by the worker. Heavier items should be tethered to a strong, fixed point such as a load rated rail or beam.

## SELF FUSING TAPE INSTRUCTIONS >

When using silicone tape - LINQ recommend a minimum of two passes of the length of the tether

### CERTIFIED TOOL ANCHOR POINTS IN 3 EASY STEPS

- **Cut:** a length of tape between 30cm-40cm (or enough to go around the tool at least 10 times).
- **Position:** the Tether Point on the tool.
- **Apply:** Self Fusing Silicione Tape, pulling it tight and without covering the Tether connections point.



Reading of LINQ instruction manual prior to use is mandatory. Description and specification subject to change without notice. If in doubt please contact the LINQ helpline.