














Heavy duty Lab chair and drafting chair




	1			1		1		A			
				1			M6*30X2				
	1		1		5		C 4		D 2		B
								M6*20X2			


Standard base assembly

STEP 1

Insert castors
into base.




Insert gas
cylinder into
base.





Drafting base assembly

STEP 1


Insert castors
into base.




Insert gas
cylinder into
base.



Insert drafting
ring over gas
as shown.



STEP 2



STEP 3

