jason.l

Quadro Loop Boardroom table




Tools Required: Power screwdriver; Allen key set (provided)

2 persons required for installation


jason.l

Quadro Loop Boardroom table




Quadro Loop Boardroom table

jason.l




Using Allen Key provided, attach 2 plastic brackets per leg **(F)** (as per picture above) using M6x20MM **(I)** Socket head screw. Do the same with Connector frame **(D)**. Connect Loop Legs **(C)** to Bottom of Quadro Legs **(B)** by using 4 bolts per leg.



Using Allen Key provided, attach M8x20MM Socket head **(H)**-screw socket half way into leg for both legs **(B)** and into Connector frame **(D)**.


Quadro Loop Boardroom table

jason.l




Quadro Loop Boardroom table

jason.l




Attach beam **(E)** to legs **(B)** and Connector frame **(D)** using nut insert in legs. See point attached




Frame looks like this. Using Allen Key, attach beam (E) with Socket (G)

jason.l

Quadro Loop Boardroom table



Place the desktop on top of the frame. Please place the legs ideally indented around 300mm from each end left and right of the Tops, Place the legs centred at the same distance equally from the front and back of the top.



Please tighten M6x30MM Socket head (1) through the plastic brackets into the underneath of the tops.