## LS4278.com

1 855-427-8684

www.LS4278.com

- Print this page.
- 2. Verify the cradle is connected to a USB port on the computer.
- 3. Allow the scanner to charge for 24 hours before first use.
- Scan barcodes 1 10 in order. Read the notes between the scans.

## Note:

#3 is the barcode on the top of the charging cradle.

#5 and #10 are test scans, place the cursor on an area of your computer you can type in to test.

**Set Factory Defaults** 

Wait a few seconds **USB** might reset

Write to Custom Defaults

Wait for Fast Blink Beep

Single-line Only



Scan Options

Wait for Beep

<DATA> <SUFFIX>

9



Enter

\*HID Keyboard Emulation Wait a few seconds **USB** might reset