

PARTS GUIDE


Please remove all parts from the boxes and review them. Contact your service representative if there are any missing parts.



GRAPHIC MOUNTING GUIDE

Step 1

Locate the silicone beading on the back side perimeter of the graphic. Insert corners of graphics into troughs of the frame to begin graphic installation. Press the silicone beading into the trough of the frame and work your way around the entire perimeter for each side.



Step 2

Repeat the same process for the other (3) graphics until all (4) are installed. Place the acrylic counter top on to the top of the frame. Make sure the alignment squares under the acrylic counter top are flush in each corner.



COUNTER


SET UP INSTRUCTIONS



INSTALLATION STEPS

Step 1


Start by building both vertical sides.



(2nd FOLD HERE)

Step 2

Take (1) 40" extrusion and (1) 22" extrusion and connect them. Lock the 22" extrusion by tightening the exposed Torx head with the supplied Torx key.



(1st FOLD HERE)


Step 3

Continue until you have (1) complete perimeter, as shown above. Repeat the same process so that you have (2) of these completed.




Step 4

Take (1) side and attach the remaining 22" extrusions.



Step 5

Once you have the remaining 22" extrusions locked in place (shown below), you are now ready to place the 2nd side that was completed in Step 3 on top.



Step 6

Tighten/lock the top and rotate the frame on to its vertical side (shown below). The frame is ready to have the graphics and acrylic counter installed.

