

LENNOX HEARTH PRODUCTS**Service Replacement Parts List****ULTRABAY (UB42)**

Gas Log Insert

MODEL YEARS: 1995 - 1996

ITEM NO	DESCRIPTION
Door Parts	
PC-0002	Glass, Front
PC-0001	Glass, Side (order 2 if set is needed)
Electrical Parts	
PB-0001	Blower, Room Air
15049	Disc, Low Limit (Blower, 60T12, F140° - 20F)
528	Rheostat, Blower Speed Control (stem of rheostat will require notching using a hack saw) ♦
PH-0007	Thermocouple (Includes Pilot Bracket Assembly)
PH-0001	Valve, Control, White Rodgers
Gas Component Parts	
MTVRN01	Burner Tube Assembly
PH-0005	Orifice, Burner - Propane #48
PH-0004	Orifice, Burner - Natural Gas #31
PH-0008	Orifice, Pilot #14
PH-0002	Pressure Regulator (Natural/Propane)
Miscellaneous Parts	
AF-0014	Handle, Control (for gas valve control)
70K99	Paint, Metallic Black (12 oz spray) *SN > 2083, 76-141MB
76-141	Paint, Satin Black (12 oz spray) *SN < 2083
30105	Insulation, Pilot (The insulation pad prevents air from pulling through floor plate and shields pilot from turbulence in firebox, thus reducing the likelihood of nuisance outages.)
501H	Pilot Upgrade Kit, *SN < 2133 **
Firebox & Log Parts	
88L53	Embers, Glowing, 1oz. Bag (order a minimum of 10 for maintenance needs)
MTVD	Log Set

* SN Stove serial number range, parts are compatible with:

">" = greater than # indicated, "<" = less than # indicated, "-" = numbers within range

♦ Rheostat is not designed to use a knob. Use bladed screwdriver to adjust to setting desired for thermal activation. Replacement rheostats will not have a notch to accept screwdriver - cut a notch using a hacksaw.

** Some 1995 and earlier models had a vertical pilot w/a smaller pilot orifice. This new pilot reduces likelihood of nuisance outages by angling pilot at 45 degrees and has a larger pilot orifice.