


IHP
Service Replacement Parts List

Tahoma™ 2100
Cat. No. H8872
Model Years: 2014 - Present



Miscellaneous Parts	
Cat. No.	Description
H8890	Right side heat shield
H8891	Left side heat shield
H8892	Back heat shield
H8893	Door back w/pins
H8894	Door channels w/nuts
H8895	Glass
H5640	Glass gasket kit (8' 4")
H5639	Door rope kit, 7/8" dia. (6' 2")
H8897	Baffles
H8898	Secondary burn tubes w/clamps
H5650	Draft rod knob
H8899	Ash lip w/hardware
H8900	Pedestal
H8901	Door handle w/hardware
H8902	Door latch w/hardware
H8896	Complete Firebrick kit
Optional Accessories	
Cat. No.	Description
H8873	<i>Blower Kit, 2100, BLWR-ES-S-150</i>
H8159	<i>Touch-Up Paint , Metallic Black, 12 oz. Aerosol, TSPK-B</i>
UZIAD	<i>Outside Air Coupler Kit (connects outside air ducting, UZI, to stove) AND ↓</i>
UZI	<i>Outside Air Ducting Kit (includes 4" insulated flex x 10' long) AND ↓</i>
H8874	<i>Outside Air Panel and Air Channel Kit (includes rear pedestal panel and side and front air channels), OUTAIRKIT-ES</i>

Note: Items in italics may be discontinued 6 months after the end of model production or later if inventory is available.

OPTIONAL BLOWER KIT



OUTSIDE AIR KITS



TOUCH-UP PAINT

