





# ASSEMBLY INSTRUCTION

## G5658 - CHEST 2 OVER 3

No	Name of Hardware	Q.ty
①	Bracket 	2
②	Tie 	1
③	Screw M4 x 20 	2

### STEP 1



### FINAL

