






# ASSEMBLY INSTRUCTION


## G5687 - CHEST 6 DRAWERS

No	Name of Component	Q.ty
A		1
No	Name of Hardware	Q.ty
1	Bracket 	2
2	Tie 	1
3	Screw M4 x 20 	2

### STEP 1



### STEP 2



### STEP 3

