

5189 WOMEN'S BRIGHAM KNIT JACKET

SIZES XS-3XL

- :: 100% Polyester yarn-dyed knit fleece in a unique space dye effect (7.37 oz/yd², 250GSM)
- :: Full zip and mock neck



Feminine Silhouette

Mock Neck

Fleece for Warmth

Binding on Collar

Full Zip Styling

BACK VIEW



Zippered In-Seam Pockets with Welded Tape

COMFORT & CONVENIENCE

- :: Full zip and mock neck
- :: Zippered inseam pockets, styled with welded tape trim, will keep items secure
- :: Women's version features a feminine silhouette, making it the perfect layering piece for any occasion

FABRIC

100% Polyester yarn-dyed knit fleece in a unique space dye effect
(7.37 oz/yd², 250GSM)

SIZES

Sizes XS-3XL

COLORS

014 Light Grey, 010 Black, 040 Navy, 199 Oatmeal

GARMENT CARE

Machine wash cold with like colors. Gentle cycle. Only non-chlorine bleach when needed. Tumble dry low. Do not iron.

DECORATION RECOMMENDATIONS

Embroidery: Ballpoint 70/10 needle. Two cutaways (no show mesh) stacked and rotated into a multipoint star. Topical Solvent recommended if small letters are included.

Heat Transfer: Max heat recommended is 305°F

Screen Printing: Automatic printing process is recommended. Maximum number of colors recommended is 8. Poly Low Bleed ink recommended for both white and dark ink colors. Catalyst recommended. Dryer temperature should not exceed 315°F.

010 BLACK

014 LIGHT GREY

040 NAVY

199 OATMEAL



BRIGHAM KNIT JACKET WOMEN'S 5189	XS	S	M	L	XL	2XL	3XL	TOLERANCE
BODY LENGTH measure from neck (CB neck)	25	25 ½	26	26 ¾	27 ½	28	28 ½	½ +/-
ACROSS SHOULDER	14 ½	15	15 ½	16 ¼	17	17 ¾	18 ½	½ +/-
CHEST WIDTH measure 1 inch below armhole	18 ½	19 ½	20 ½	22	23 ½	25 ½	27 ½	½ +/-
BOTTOM OPENING WIDTH RELAXED 1/2	19 ½	20 ½	21 ½	23	24 ½	26 ½	28 ½	½ +/-
SLEEVE LENGTH measure from CB	31 ¾	32 ¾	33	33 ¾	34 ½	35	35 ½	¼ +/-

KEY TO COMMONLY ABBREVIATED SPEC INFORMATION (ALL MEASUREMENTS ARE IN INCHES)

CB = CENTER BACK

CHEST 1 INCH DOWN = MEASURE THE FRONT OF THE GARMENT 1 INCH DOWN FROM THE ARMHOLE

1/2 = MEASURE ONLY THE FRONT OF THE GARMENT, THEN DOUBLE THAT MEASUREMENT TO GET THE TOTAL CIRCUMFERENCE

RELAXED = DO NOT STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, SIMPLY LEAVE THE ELASTIC RELAXED

STRETCHED = STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, MEASURE STRETCHED