

Aputure®

**Amaran**  **Lighting Up**

AL-M9

**Product Manual**

English

## Instructions

- For security, please do not leave the product in excessive heat areas or expose in moist conditions.




**WARNING:** Avoid storing the lamp where there are corrosive chemicals.

- Please have the product checked by an authorized service or agent if your product has a problem. The malfunctions caused by your no allowed disassembling are not under the warranty.
- The product is certificated by RoHS and CE. Please operate the product in full compliance with the operation standards. Please note that this warranty does not apply to repairs arising from malfunction, although you may request such repairs on a chargeable basis.
- The instructions and information in this manual are based on thorough, controlled company testing procedures. Further notice will not be given if the design change.

## Components

### 1. Light



① Lamp beads

② Magnet column

③ USB Charging Port


④ Brightness “-” button

⑤ Brightness “+” button


⑥ Power switch

⑦ Indicator


## 2. Accessories



Diffuser



Universal Adapter



Carrying Case



USB Charging Cable




Product Manual





Warranty Card

## Installation

1. Install the diffuser on the lamp body.





2. Place the lamp in the universal adapter, then fix the screw clockwise.




### 3. Diagram


1) Install the lamp with cold shoe.



2) Disassemble the cold shoe, then use the thumbscrew to install the lamp with 1/4 screw into camera's 1/4 screw hole.




3) Handheld



# Operations

## 1. Charging




\* The indicator lights red in charging ,then goes off when the lamp is fully charged.

\* The indicator flashes red a few times, the lamp will automatically shut down.


\* The indicator lights blue in working time.

## 2. Power ON/OFF



### 3. Adjust the Brightness

Short press “+” and “-” buttons to change the brightness, long press “+” or “-” buttons to switch the brightness quickly.



### Specifications

Color Temperature		5500±200K		
CRI		>95		
TLCI		>95		
Illuminance	Distance	0.3 m	0.5 m	1 m
	Brightness	≥900LUX	≥350LUX	≥80LUX
Number of LEDs		9		
Battery Type		Lithium-polymer battery(3.7V 1800mAh)		
Voltage		DC 5V		
Current		1A		
Battery Working Time		>1.75h (maximum brightness)		
Dimension		87*56*11 mm		

Detailed product manual for AL-M9 can be found on the movie solution page on [www.aputure.com](http://www.aputure.com).