

# Benchtop table saw Workstation

## Materials & Hardware

<b>A</b> Sides (2)	725 x 610 x 19 Ply.	<b>U</b> Infeed Supports (2)	610 x 150 x 19 Ply.
<b>B</b> Bottom & Shelves (5)	760 x 591 x 19 Ply.	<b>V</b> Support Stops (2)	300 x 50 x 19 Ply.
<b>C</b> Back (1)	760 x 480 x 19 Ply.	<b>W</b> Legs (4)	880 x 90 x 19
<b>D</b> Lower Supports (2)	591 x 170 x 19 Ply.	<b>X</b> Rails (4)	760 x 90 x 19
<b>E</b> Middle Supports (2)	591 x 45 x 19 Ply.	<b>Y</b> Tops (2)	820 x 90 x 19 rgh.
<b>F</b> Upper Supports (2)	591 x 90 x 19 Ply.	<b>Z</b> Runners (4)	685 x 90 x 19
<b>G</b> Drawer Front/Back (2)	658 x 140 x 19 Ply.		
<b>H</b> Drawer Sides (2)	570 x 140 x 19 Ply.		
<b>I</b> Drawer Bottom (1)	670 x 552 x 19 Ply.		
<b>J</b> False Front (1)	716 x 164 x 19 Ply.		
<b>K</b> Cleats (2)	610 x 38 x 19 Ply.		
<b>L</b> Tops (2)	610 x 75 x 19 Ply.		
<b>M</b> Right Wing (1)	610 x 520 x 19 Ply.		
<b>N</b> Left Wing (1)	610 x 655 x 19 Ply.		
<b>O</b> Top Cover (2)	610 x 75 Plastic Lam.		
<b>P</b> Right Wing Cover (1)	610 x 520 Plastic Lam.		
<b>Q</b> Left Wing Cover (1)	610 x 655 Plastic Lam.		
<b>R</b> Wing Tracks (4)	610 x 57 x 50		
<b>S</b> Wing Braces (2)	710 x 590 x 19 Ply.		
<b>T</b> Support Cleats (2)	610 x 50 x 19 Ply.		

- (16) 8g x 50mm c/s Woodscrews
- (16) 8g x 32mm c/s Woodscrews
- (10) ¼" Threaded Inserts
- (4) ¼" x 75mm Hex Head Bolts
- (4) ¼" Hex Nuts
- (4) 125mm Locking Swivel Castors
- (16) ¼" x 25mm Lag Screws
- (2) 508mm Full-Extension Drawer Slides w/Screws
- (2) 28 x 610mm Continuous Hinges w/Screws
- (1) 1200mm T-Track w/Screws
- (6) ¼" Washers
- (6) ¼" Star Knobs
- (1) ¼" x 330mm Threaded Rod

## Cutting Diagram


2400 x 100 x 19 Clear Stock (Four boards)



1800 x 100 x 19 Clear Stock




2400 x 140 x 19 Clear Stock (Two boards)




ALSO NEEDED: 1200 x 1200 SHEET OF PLASTIC LAMINATE

1200 x 1200 x 19 B/B Grade Plywood



2400 x 1200 x 19 B/B Grade Plywood



2400 x 1200 x 19 B/B Grade Plywood

