


# Appendix 1— Platform Bed / Mattress Foundation Guidelines

## Example 1: Mattress Warranty Approved Platform Bed Frame and/or Mattress Foundation

This is an example only. The platform bed frame and/or mattress foundation requirements for the Mattress Warranty can be met with a slat distribution other than what's diagramed in Example 1 provided a few basic guidelines are followed.

For Mattress Warranty approval **ALL** of the following conditions below must be met for a platform bed frame and/or mattress foundations purchased through a third party. If any of the conditions are not met, or cannot be independently verified (eg. covered mattress foundation), Nature's Embrace reserves the right to **VOID** the Mattress Warranty.

- 1) The spacing between the slats must be no greater than 3" (A)
- 2) The spacing between the slats can't be greater than the width of the slats (A cannot be greater than B)
- 3) The slat width must be no less than 2" (B)
- 4) The slats must be at least 3/4" thick.
- 5) The slats are supported by a full length mid-rail (C)
- 6) At least one mid-rail support (runs from the bottom of C to the floor)




## Example 2: Platform Bed Frame and/or Mattress Foundation That Will VOID the Mattress Warranty

This is an example only. **ALL** conditions as described in the Mattress Warranty and Example 1 must be met for Mattress Warranty claims on Nature's Embrace Mattresses used in conjunction with a platform bed frame and/or mattress foundations purchased through a third party. If any of the conditions are not met, or cannot be independently verified (eg. covered mattress foundation), Nature's Embrace reserves the right to **VOID** the Mattress Warranty.

Reasons the platform bed frame and/or mattress foundation diagramed in Example 2 will **VOID** the Mattress Warranty are:

- 1) The spacing between the slats is greater than 3" (A)
- 2) The spacing between the slats is greater than the width of the slats (A is greater than B)
- 3) The slat width is less than 2" (B)
- 4) The slats are not supported by a full length mid-rail
- 6) There is no mid-rail support



If you are unsure if your platform bed frame and/or mattress foundation, or any platform bed frame/mattress foundation, meets our guidelines, they can be approved in writing by emailing pictures and/or detailed specifications to [info@nelatex.com](mailto:info@nelatex.com)