

OGW-1 Oil Gallery Wax Instructions

GOODSON

Tools and Supplies for Engine Builders

156 Galewski Drive • P.O. Box 847 • Winona, MN 55987-0847

Toll-Free 1-800-533-8010 • Local 507-452-1830 • www.goodson.com

OGW-1

Please read instructions before using.

Instructions

1. Preheat the part to be removed until it is red hot.
2. Let it cool just long enough for the red to disappear.
3. Apply Oil Gallery Wax to the base of the threaded part.
4. Remove part.

Contents

6" sticks. Quantity of 10

OGW-1

Galería Aceite de Cera Instrucciones

GOODSON

Herramientas y suministros para reestructores de motores

156 Galewski Drive • P.O. Box 847 • Winona, MN 55987-0847

Toll-Free 1-800-533-8010 • Local 507-452-1830 • www.goodson.com

OGW-1

Por favor de leer las instrucciones antes de usar.

Instrucciones

1. Precalear la parte que va ser retirado hasta que se mire rojo en caliente.
2. Dejar que se enfríe la parte suficiente que lo rojo se desaparece.
3. Aplicar la galería de aceite de cera a la base de la parte roscada.
4. Retirar la parte.

Contenidos

Barras de 6". 10 en Cantidad.

Junio 2012