

# 1964-67 CUTLASS



Photo 1




Photo 2

Handle removed from shifter base. The tab that must be ground down to a more narrow profile is easily seen in Photo 2 on the right side.



Photo 3



Photo 4

Photo 3 shows the width of the tab prior to grinding, and photo 4 shows the tab after reduction.