


www.evotech-performance.com Yamaha MT-10 SP Oil Cooler Guard Instructions







121/135



U

Repeat Both Sides


O









4 3300 9 Repeat Both Sides











6











R





It is recommended that periodic inspections are made to ensure that dirt and debris have not become trapped between the guard and the radiator/oil cooler. Such dirt and debris would reduce the cooling efficiency of the radiator/oil cooler.

It is recommended that periodic inspections are made to ensure that all fixings are fully tightend.





www.evotech-performance.com