#### Wedge Data Application User Guide

Download and install the 232 Key wedge data application onto the computer you will be connecting the bottle weigh scale to. An installation link is located in the email you received with this guide attached or you can optionally enter the following URL into your browser address bar and hit enter to download.

https://www.232key.com/software/232key-setup.exe

Once the application download (35.6 MB) is completed, run the software and proceed with the installation process.



cense agreement		100	
Installation and use of 232key agreement:	2018.1 requires acceptance	of this license	
Grant of license and copyrigh	nt		^
The material contained in this copyright holder) grants a lice the conditions listed below. The parties which retain the conditions are the conditions of th	s release is licensed, not sold. ense to the person who instal he software may include mate wight on those materials	Smartlux SARL (the s this software, su erials developed by	e bject to third
paraco, which retain the copy	right on alose materials.		
Installation	fight of a lose matchais		
Installation This software is licensed to er computers.	nd users for installation on ge	neral purpose de <mark>s</mark> k	top
Installation This software is licensed to er computers. Distribution	nd users for installation on ge	neral purpose desk	top 🗸
Installation This software is licensed to er computers. Distribution I accept the terms of the license	nd users for installation on ge cense agreement	neral purpose desk	top V
Installation This software is licensed to er computers. Distribution I accept the terms of the lice I do not accept the terms of	nd users for installation on ge cense agreement of the license agreement	neral purpose desk	top V

232key 2018.1 - Excelsior Installer		- I	1	×
Installation type				
Choose installation type				
Install this application for:				
O Current user only				
Anyone who uses this computer				

NEX 1821 1021220				1977	105 14
estination folder					
Select destination folder					
The installer will install 232key 20	18.1 compone	ents to the follo	wing folder.	200	
To install to this folder, dick Next	t.				
To install to a different folder, di	ck Browse and	d choose anoth	er folder.		
Destination folder				12	
Destination folder C:\Program Files (x86)\232key				Browse.	
Destination folder C:\Program Files (x86)\232key Space required on C:				Browse. 9	 1584 K
Destination folder C:\Program Files (x86)\232key Space required on C: Space available on C:				Browse. 9 89494	 1584 K 3560 K

rogram folder		1	
Select program folder			
The installer will add program icons to the pro folder name or select one from the list of exis	ogram folder listed b sting folders. To con	elow. You may	type a new
232key			
Accessibility			^
Accessories Administrative Tools			
AVG Zen			
Corel PaintShop Pro X8			
CyberLink Media Suite			
Dell Audio			
EPSON			~
			in the second se
Install	< Back	Next >	Cancel

232key 2018.1 - Excelsior Installer		275 Å		X
Start installation		-	1111	
View current settings				
The installer is ready to install 232key 2018.1 on your comput- installation or Back to change the current settings listed below	ter, Click Ne v.	ext to beg	gin the	
Current settings: Destination folder				~
C:\Program Files (x86)\232key				
Program folder				
232key				
				~
			-	



### Select Finish

Now that the wedge data application has been installed on your computer, you can find it by looking for the newly installed program 232key. Each time you will be weighing, after you plug the BC8200 scale into your computer, launch the 232key program.

**IMPORTANT:** You must plug the scale into your computer before launching the wedge data application so it can read the USB port that the scale is plugged into. The first time using the wedge data software you will need to make one change.

After launching 232key for the first time, proceed as follows:



# Application is opening



# Start Screen

# From the start screen select the "Output" tab.

Start/Stop Input P	rocess	Output	Settings	Event	t Log	About	License		
Keyboard:	US (C	WERTY)				~			
Delay:*	20	ms t	etween ch	naracte	rs				
Decimal separator:	Dot	~							
Start with:*	None	~							
End with:	None	~	alternate	with*	None	~	every	values	5
Sound:~	None								

# **Output Screen**

tart/Stop Input P	Process	Output	Settings	Even	tlog	About	License		
and top input i	100033		occuriga	LVCI	it Log	About	cicciliac		
Keyboard:	US (C	WERTY)				$\sim$			
Delay:*	20	ms t	between <mark>c</mark> h	naract	ers				
Decimal separator:	Dot	~							
Start with:*	None	~							
End with:	None	~	alternate	with*	None	0	every	va	alues
	None		S						
Sound:*	Enter								
	TAB								
	Right								
	Down	20							
	Comm	a							
	Semic	olon							
	Space		2						
* DI									

#### **Output Screen**

#### Select the drop down next to End With:

Choose the "Enter" option. This is the function that will take place after the weight is transferred from the scale to the inventory program.

By selecting "Enter", after a weight is transferred the product cell below it will automatically be selected and ready for the next product to be weighed.