



FARM DUTY

CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION.

REV. DESC: LEAD HOLE SHOULD BE 1.09 NOT 1.06		
REV. LTR: B	VERSION: 02	TDR: 000001030371
FILE: \AAA\00205\904	REVISED: 09: 35: 54 05/31/2017	BY: ENBILTO
MTL: -		

BALDOR

HORZ 182-184TZ TEFC 36M, V=3.75, SEAL PU END, FARM DUTY

SH 1 of 1

36LYQ180