


A-C MOTOR CONNECTION DIAGRAM PART WINDING START



(N.P. 1767-1-A)

REV. DESC: -ADDED JUMPERS TO "RUN" CONNECTIONS

REV. LTR: A

VERSION: 01

TDR: 00000558689

FILE: \MGA\00000\668

REVISED: 09:44:55 09/20/2010

MTL: -

BY: MGH TLC

BALDOR

CONN DIAG - PART WINDING START

SH 1 of 1