

T1 (U1) → L1 T4 (U2) ———


T5 (V2) — T6 (W2) -

RUN

T1 (U1) T6 (W2) -T2 (V1) -T4 (U2) -T3 (W1) -T5 (V2) -

NOTE: IEC LEAD MARKINGS ARE NOTED IN PARENTHESES

THREE PHASE - Y START A RUN MOTOR



VIEW OF TERMINAL END

				TOLERANCES UNLESS SPECIFIED		//inen/in		DRAWN BLR 10-04-1999		
				DEC.	INCHES	MOTORS		CHK DR	RS 10-04	-1999
				.x	±.1			APPD TB	10-04	-1999
3	REVISED TO MATCH M.E. ORIGINAL	TAT 07-25-2005	ML	.xx	±.02	TITLE CONNECTION DIAGRAM		SCALE	1=1	
2	REVISED DRAWING MISTAKE CN 29200-2980	ERH 05-15-2003	ML	.xxx	±.005	30 — WYE START DELTA RUN		REF		
1	NEW DRAWING	BLR 10-09-1999		.xxxx	±.0005	MAT'L.		FMF		
NO.	REVISION	BY & DATE	СНК	ANG	±7'30"	FINISH		PREV		
THIS DRAWING IN DESIGN AND DETAIL IS OUR PROPERTY AND MUST NOT BE USED EXCEPT				RFP		CAD FILE ee7340 In	SIZE DRAWING NO	. PAGE	OF	REV.

IN CONNECTION WITH OUR WORK ALL RIGHTS OF DESIGN AND INVENTION ARE RESERVED THIS IS AN ELECTRONICALLY GENERATED DOCUMENT - DO NOT SCALE THIS PRINT

DIST WA-LB-SB

EE7340-LN

T4C

9/30/2008 5:41:56 AM