




912577

Motor Wiring Diagram 6 Lead, Single Phase, Dual Voltage



Connected for CW Rotation Facing Shaft End.
To reverse direction of rotation, interchange leads 5 & 8.

Each lead may have one or more cables comprising that lead.
In such case, each cable will be marked with the appropriate lead number.