

## Climate control with DL-FM6 or RS-FM6

When using DL-FM6 or RS-FM6, the vehicle's climate system defaults to AUTO MODE during remote start. This setup cannot be changed or modified. Please carefully read this excerpt from the vehicle owner's guide:

- In hot weather, the system is set to 72°F (22°C).
- In moderate weather, the system either heats or cools (based on previous settings). The rear defroster, heated mirrors and heated seats are not automatically turned on.
- In cold weather, the system is set to 72°F (22°C). The heated seats are set to high (if available, and selected to AUTO in the information display). The rear defroster and heated mirrors are automatically turned on.'

**IMPORTANT: IF THE CLIMATE SYSTEM CONSISTENTLY BLOWS COLD AIR ONLY DURING REMOTE START, THE VEHICLE MAY BE SUBJECT TO THE FOLLWING TSB FROM FORD AND SERVICING MAY BE REQUIRED.**



**CLIMATE CONTROL SYSTEM BLOWS COLD AIR DURING REMOTE START EVENT - DEFROST NOT SELECTABLE UNDER REMOTE START MENU - INSTRUMENT CLUSTER**

**TSB 14-0096**

**FORD:**

2013-2014 Fusion

**LINCOLN:**

2013 MKZ

This article supersedes TSB **13-5-28** to update the vehicle model years and include the software for Single Zone Manual Temperature Control vehicles.

**ISSUE**

Some 2013 Fusion and MKZ vehicles equipped with Remote Start and Dual Zone Automatic Temperature Control built on or before 4/16/2013, and 2013-2014 Fusion vehicles equipped with Remote Start and Single Zone Manual Temperature Control may exhibit a concern of the climate control system blowing cold air during a remote start event. In addition, the defrost option may not be available in the Instrument Cluster Settings - Remote Start Menu.

**ACTION**

Reprogram the Front Controls Interface Module (FCIM) to the latest calibration using IDS release 90.02 and higher. Calibration files may also be obtained at [www.motorcraft.com](http://www.motorcraft.com).

OPERATION	DESCRIPTION	TIME
140096A	2013-2014 Fusion And 2013 MKZ: Reprogram The FCIM, Includes Time To Clear Codes (Do Not Use With Any Other Labor Operations)	0.3 Hr.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage  
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
19B555	42