


OP-916 FLOOR SCALE ASSEMBLY GUIDE



Inside Scale:

- (1) Homerun Cable
- (1) Indicator w/ U-bracket
- (1) AC Adapter
- (1) Indicator manual
- (4) Screw in Feet

1. Carefully open box and remove scale
2. Locate access compartment (Top or Side) and remove the screws
3. Remove all contents from inside compartment
NOTE: any upgrades to the order will be shipped separately, ie. indicator w/battery
4. Route the homerun cable through the cable opening located inside the compartment near the underside of the scale
5. Close compartment latch with screws
6. Screw in all 4 feet into the 4 load cells located on the underside of each corner
NOTE: Do not screw in too deep that it will touch the platform
7. Place scale on flat surface, if not level, lift scale slightly and adjust scale feet with a screwdriver through the feet access openings until the scale is stable
8. Connect the homerun cable to the indicator
9. Plug the AC adapter to the indicator and power on the indicator
10. Once indicator is powered on, the display will count down show zero
11. To ensure your scale is level, place an item you know the weight of on each corner of the scale, if a corner varies, adjustments to the feet should be made
12. Your scale is ready for use (no calibration is needed)
13. If the weight is incorrect, calibration will be needed

NOTE: Please refer to your indicator manual for proper calibration steps

Please call 844-735-5386 for information

For updated indicator manual, please refer to www.selletonscales.com/pages/downloads