



Rotation Spindle Refurbishment



Overview

Our service technician will disassemble and inspect the complete assembly for damage and wear. "Standard" wear parts are replaced and new assembly bearings are lubricated. Additional damaged machined parts are recommended and quoted to the customer a la card. Customer chooses which parts and upgrades to purchase à la carte, post inspection.



Standard Replacement Parts

- 1 QTY BEARING, 3.0IDx3.5OD
- 1 QTY DUAL BEARING, DUPLEX PAIR SPINDLE
- 1 QTY DUAL BEARING 6007RU (6007 VV C3)
- 1 QTY BEARING, 25IDx.625OD
- 4 QTY O-RING .145 ID X .070 CSD
- 1 QTY WSHR WAVE SPRG 3.62OD X 3.19ID X .27FH SST
- 4 QTY SCR CAP FLT HD 4-40 X 1/4L PHIL SST
- 6 QTY SCR CAP SKT HD 8-32 X 3/8L HEX SKT SST
- 6 QTY SCREW, SHCS, 4-40 X 1/4, SS
- 1 QTY IN COMING INSPECTION REPORT FOR MIRRA ROTATION SPINDLE





To Find Out More Or To Place An Order See Our Links Below.

To see more part details on the rotation spindle refurbishment click the our video icon.



To email Entrepix parts or to get additional parts information click icon.



To explore, shop and download part information click icon.



To call Entrepix parts dial or click. icon

