



RJ45 Female to USB connector in DCU Wiring Diagram

BRN/WHT	4	_____	1 (Tx/Rx(+))
BRN	5	_____	6 (Tx/Rx(-))
BLU/WHT	6	_____	5 (+12V DC)
BLU	7	_____	2 (+12V DC)
GRN/WHT	8	_____	3 (-12V DC)
GRN	3	_____	4 (-12V DC)



RS485/USB adapter to Modbus Module Cat 5e CONNECTION DIAGRAM



Wiring RS485/USB adapter to Modbus Module Cat 5e

WHT/BRN Tx+/Rx+(PIN4) ————— USB adaptor Connector "B"
 BRN Tx-/Rx-(PIN5) ————— USB adaptor Connector "A"

