

AgSolutions Rear Wear Kits MOUNTING INSTRUCTIONS

PRODUCT DESCRIPTION

A Poly wear strip to repair already damaged snouts or to help premature wear. Strips are molded for an exact fit design made with high friction tested material to last a very long time in the field. Smooth finish design will ensure quality, even flow when combining.

- 1. Always be sure header is in lock or safe position before working under or around header.
- 2. Simply position wear panel over worn area of the snout or approximately in the middle of the snout as shown.



3. It is recommended to place the wear panel near the center of the snout making sure the bottom of the wear panel and the bottom of the snout is in line as shown.



4. With the hardware provided install the self tapping screws in each of the predrilled holes on the wear panel.

