


These wires from wall plug & chord
110 OR 220 Volt


"L" "N" Gnd



L N Ground

These Three Wires To Motor
IGNORE WIRE COLORS HERE!
****WIRES ARE LABELED****

"W" "V" "U"




W V U



Wires enter and exit at this end

4 Large Capacitors

small screw terminals



These Five Wires To Motor



plug & socket from harness


DRIVER-1500W

110 VOLT DRIVE IS GXT02029-110-2-----220 VOLT DRIVE IS GXT02029-220-2


Note: Wire colors are subject to change. Use wire markings.

GRANITE XT CONTROL WIRING SMITHY INDUSTRIES	1500W DRIVER & CONTROL 110-VOLT & 220 VOLT	DRAWN: DEW	Revision	Page 1 of 2
		DATE:2019-03-08	A 03/08/19	


Driver Sockets




Plug To Large Driver Socket



Power Plug for Tachometer




Potentiometer



Reset Button

Wire Bundle



Note: Wire colors are subject to change. Use wire markings.

GRANITE XT CONTROL WIRING SMITHY INDUSTRIES	LOW VOLTAGE CONTROL SWITCHES 110-VOLT & 220 VOLT	DRAWN: DEW	Revision	Page 2 of 2
		DATE: 2019-03-08	A 03/08/19	