

## AFTER-SALE SERVICE

Purchase Date	(Year)	(Month)	(Date)
Warranty Period			
Purchase Store			

Please paste the store's stamp and guarantee barcode here, Please notice the purchase date should be confirmed when you buy the product.

## WARRANTY SERVICE

Issues	Solution
Separate bulb	Light off: Defective bulbs: Please switch a new set bulbs with your drivers, if it works well that means the bulbs is defective, please contact us for the replacement.
	Unusual light: It's not quality problem but required a decoder.
	Flicker: It's not quality problem but required a decoder.
	Lights flicker while driving: It's not quality problem but requires more space for heat dissipation.
ALL in one bulb	Flicker: It's not quality problem but required a decoder.
	Light off: Please make sure the installation is correct, if the bulbs still not work after checked, please contact us for the replacement.
	Unusual light: It's not quality problem but required a decoder.
	Lights flicker while driving: It's not quality problem but requires more space for heat dissipation.

### Attention:

The following conditions are beyond warranty scope.

1. Canbus problem: when replace the original halogen bulb with LED bulb, some vehicles may meet with canbus problem like light flickering etc, please connect suitable decoder to solve the canbus problems.
2. Man-made reason: man-made reason lead to broken led chip, chapped wire, user modify or repair the bulb themselves etc.
3. Installation problem: some vehicles may can not install our product because of small installation space or installation position doesn't fit etc.
4. Natural disaster: damage because of irresistible natural disaster like earthquake, flood etc.


## WARRANTY SERVICE

Thank you for being the best part of NOVSIIGHT.

Please contact us if there is any problem with headlights, we will response you in 24 hours.




**NOVSIIGHT**  
AUTO LIGHTING




PRODUCT MANUAL


## H7




1 Take out the retainer clip from NOVSIIGHT




2 Insert retainer clip on the socket



3 Insert and twist to lock NOVSIIGHT bulbs




4 Connect the plug




### Tips

Please contact us if the cord is not long enough to connect.


## H1/H3/H4




1 Release the spring from the bulb



2 Insert NOVSIIGHT bulbs




3 Fix bulb with spring




4 Connect plug and done


## H8/H9/H10/H11/H13/9004/9005/9006/9007/880/881



1 Insert NOVSIIGHT bulbs



2 Twist the bulbs on clockwise



3 Connect the plug and done.

## PRODUCT SPECIFICATION

Operating Voltage	DC9-32V
IP Rate	IP68
Light Source Model	7535
Color Temperature	6500K
Heat Dissipation Theory	Aviation aluminum ADC12
Operating Life	>100000hrs
Operating Temperature	-40°C~+80°C