

P.O. Box 340 Eastpointe, MI 48021 P: (586) 771-4610 F: (586) 771-5527 www.lytepoles.com	DRAWN: M. HARVALA	2/16/2015		SOME GEOGRAPHICAL AREAS HAVE SPECIAL WIND CONDITIONS THAT CAN CREATE WIND INDUCED VIBRATIONS CAUSING & FATIGUE PROBLEM. NO METHOD HAS YET BEEN FOUND FOR PREDICTING DESTRUCTIVE LIGHTING POLE VIBRATION. THESE CONDITIONS ARE UNIQUE AND CANNOT BE GUARANTEED AGAINST, AND ARE THE RESPONSIBILITY OF A LOCAL SITE ENGINEER. TITLE: CATALOG:		180°
	CHECKED		DESTRUCTIVE LIGHTING POLE VIBRATION. THESE			
	REVISION:	DATE:				
	APPROVED:					
	-5527 QUOTE:		CATALOG:			1 🐺
	S.O.#		DIAC NO:			0°
a DWM company	REF:	SCALE: NONE	DWG NO: WN	SIZE C	SHEET 1 OF 1	HANDHOLE
4	3	4	2	ſ		1