DINSMORE
VALLEY MILLS
MELTHAM
HUDDERSFIELD
HD9 4AP

## F.R. BACKCOAT TEST REPORT

CUSTOMER. AMBASSADOR TEXTILES

QUALITY. GRAMPIAN
CORGI/WESTIE/DACHSUND/BEAGLE/BEDLINGTON/BERMESE/BICHON/BORDER/CORGI/H
ARRIER/BRITTANY/PAPILLION/BASSET/CAVALIER/SETTER/SPRINGER, ARRAN
OATMEAL/NICKEL/TRUFFLE/DAWN, AVALON OATMEAL/BLUSH/MINK/GLACIER/DK
SHADOW/MIDNIGHT/JADE/TEAL/MID BLUE/DK BROWN

I.D. 23/11/22/ P/O P/O M10245/47

BATCH No: **AMB 16729** 

IONUTION

**REPORT 16577** 

PASS.

THE FURNITURE AND FURNISHINGS (FIRE) (SAFETY)
REGULATIONS 1988 – AMMENDED 1989 AND 1993.
SCHEDULE 4 PART 1 – CIGARETTE TEST FOR VISIBLE COVERS.
SCHEDULE 5 PART 1 – MATCH TEST FOR VISIBLE COVERS.

THE FABRIC WAS PRE-SOAKED AND CONDITIONED AS SPECIFIED PRIOR TO TESTING OVER A 22Kg/m3 L.R. FOAM.

#### **TEST RESULTS**

SOURCE	COMMENTS	RESULT
Cigarette 0.	Cigarette consumed in 16 minutes 40 Seconds	PASS.
Match 1. 1st.	Fabric self-extinguished as flame source removed	PASS.

The above test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use. It is the Customers responsibility to ensure the suitability of the material prior to use.

Match 2. 2<sup>nd</sup>. Fabric self-extinguished as flame source removed

Signed: Richard Horn. R. HORN Dated: 7/12/22

DINSMORE
VALLEY MILLS
MELTHAM
HUDDERSFIELD
HD9 4AP

#### F.R. BACKCOAT TEST REPORT

# CUSTOMER. AMBASSADOR TEXTILES

QUALITY. GRAMPIAN BEAGLE/BEDLINGTON/BORDER/BERNESE/BRITTANY, ARRAN NAVY/OYSTER

I.D. 13-3-23 P/O P/O M10304

BATCH No: AMB 16843 REPORT 16692

THE FURNITURE AND FURNISHINGS (FIRE) (SAFETY)
REGULATIONS 1988 – AMMENDED 1989 AND 1993.
SCHEDULE 4 PART 1 – CIGARETTE TEST FOR VISIBLE COVERS.
SCHEDULE 5 PART 1 – MATCH TEST FOR VISIBLE COVERS.

THE FABRIC WAS PRE-SOAKED AND CONDITIONED AS SPECIFIED PRIOR TO TESTING OVER A 22Kg/m3 L.R. FOAM.

## **TEST RESULTS**

IGNITION SOURCE	COMMENTS	RESULT
Cigarette	Cigarette consumed in 17 minutes 00 Seconds	PASS.
	1 <sup>st</sup> . Fabric self-extinguished as flame source removed 2 <sup>nd</sup> . Fabric self-extinguished as flame source removed	PASS. PASS.

The above test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use. It is the Customers responsibility to ensure the suitability of the material prior to use.

Signed: Richard Horn. R. HORN Dated: 24/3/23