

Customer Service

N. America: 1-888-538-8683
 Local (Wyoming, USA): 307-222-6086
 Email: help@mybrewista.com



READ THIS MANUAL PRIOR TO FIRST USE AND SAVE FOR FUTURE REFERENCE

1-year Limited Warranty

Thank you for purchasing the Brewista® Smart Brew™ Coffee Scale with Timer. With proper care and treatment, this scale will provide years of reliable service.

Smart Brew™ Coffee Scale Components

- 1 Stainless steel platform
- 2 START/STOP timer
- 3 UNITS button
- 4 LCD readout
- 5 Timer reading
- 6 Battery level indicator
- 7 Weight reading
- 8 Units display
- 9 Power button
- 10 TARE button




Fig. A: Illustration of the Scale's Components and Controls

General Maintenance and Care

- Avoid exposure to extreme heat or cold.
 - Always allow your scale to acclimate to normal room temperature before use.
- Keep your scale in a clean environment.
 - Excessive dust, dirt, vibration, air currents, as well as close proximity to other electronic equipment may have an adverse effect on the accuracy and reliability of the scale.
- Handle the scale with care.
 - Set all items to be weighed gently on the top of the platform.
 - Although this scale is designed to be quite durable, avoid rough treatment as this may permanently damage the internal components.
 - Always avoid violent shaking and dropping.
 - This is a precision instrument and should be handled as such.

Unit of Measurement

- The default unit of measurement of your Smart Brew™ Coffee Scale is grams.
- Switch the unit of measurement from grams to ounces by pressing the UNITS button (3). Repeat this step to toggle back to measuring in grams.

Auto-Off Feature

- After 10 seconds of inactivity, the LCD's backlight will turn off, but readings will still be visible.
- After 5 minutes of inactivity, the scale will turn off automatically to conserve battery power.
- When the timer function is active,
 - The timer will reach 9'59" and flash before automatically turning off the scale
 - If timer is stopped before reaching 9'59", time will be displayed. After 5 minutes of inactivity, the scale will turn off automatically.

Specifications and Functions

- Capacity: 2000g / 70 oz.
- Accuracy: 0.1g for weights less than 1000g; 1g for weights 1000g to 2000g
- Units: grams (g) or ounces (oz)
- Key functions: Power, START/STOP Timer, UNITS, TARE
- Display: LCD with backlight
- Auto-off: Scale will turn off automatically after remaining idle for 5 minutes.
- Timer: Measures up to 9 minutes, 59 seconds.
- Power: (2) AAA batteries

Battery Installation

- 1 Open the battery compartment cover on the bottom of your scale and install two AAA batteries matching the positive [+] and negative [-] ends to the appropriate terminals.
- 2 The scale will automatically turn on to verify the battery installation.
 - We recommend turning off the scale when not in use to conserve battery power.

Operation

Please note: When removing weight from scale, do not apply downward force to the platform. Doing so may result in inaccurate readings.

Weight Measurement

- 1 Place the scale on a flat, level surface to ensure accurate readings.
- 2 Press the Power button (9) one time to turn on your Smart Brew™ Coffee Scale.
 - After 2 seconds, LCD will show "0.0g".
- 3 Place the item or items to be weighed on the circle in the center of the scale's platform (1). Weight will be shown on the right side of the LCD readout (4).
 - Scale measures weights up to 999.9g in increments of 0.1g. For items weighing 1000g to 2000g, the scale weighs in increments of 1g.
 - To ensure accurate readings, be sure to center your item(s) over the circle on the scale's platform.

Tare Function

- 1 Place the container on the scale's platform (1). The LCD readout (4) will show the weight.
- 2 Press the TARE button (10) one time. The weight reading will return to "0.0".
- 3 Add coffee, beans, or grounds to your container on the platform (1). The weight of the added ingredients will be shown on the right side of the LCD (4).
 - **Note:** Weight of tared container is included in the scale's maximum capacity.

Using the Timer

- 1 Press the START/STOP button (2) to start the timer.
- 2 Press the START/STOP button (2) again to pause the timer.
- 3 Press the START/STOP button (2) a third time to reset the timer to 0'00".
- 4 If the timer is not stopped or reset before reaching the maximum time of 9'59", the time 9'59" and text "Min" and

Calibration

- 1 Press the Power button (9), then immediately press the TARE button (10) three times, then press and hold the TARE button (10) for 3 seconds to access the calibration function.
 - The LCD (4) will show the sensor interior code. Each scale has a different code.
- 2 Press the TARE button (10).
 - The LCD (4) will read "2000g"
- 3 Press the TARE button (10) a second time.
 - LCD (4) will flash "2Er0" and then flash "1000g"
- 4 Place a 1000g calibration weight on the platform (1).
 - LCD (4) will show "2000g".
- 5 Place a total of 2000g in weight on the platform (1).
 - The scale will power off and the LCD (4) will show "PASS" for one second.
 - The scale will exit calibration mode and return to normal operation.

Safety Warnings

- To avoid damage to the scale, do not weigh items above the maximum capacity of 2kg.
- Items should be removed from the scale's platform when finished weighing. Do not keep items on the platform for long periods of time.
- Do not allow children to play with the scale or its batteries. Battery ingestion is very dangerous. If batteries are accidentally swallowed, call emergency medical services immediately.
- The batteries in this product cannot be reused once they lose charge.
- To avoid suffocation, do not allow children to play with the scale's packaging materials.
- This scale is not designed for user repair or maintenance outside of what is described in this manual. Repair and maintenance work should be carried out by customer service personnel as recommended by the manufacturer. Contact Brewista by email at help@mybrewista.com for more information.

"Sec" will flash for 5 seconds then the scale will power off automatically.

Turning off the Scale

- When the timer area of the LCD (4) reads 0'00" or the time is paused, press Power button once to turn off the scale.
- If the timer is still running, press and hold the Power button (9) for 2 seconds to turn off the scale.

Warning Messages


- "EEEE": Overload
 - Weight on platform exceeds the maximum capacity of 2,000g. Quickly remove weight from platform (1) to protect the scale.
- "Lo": Battery power is low.
 - Replace batteries as soon as possible to maintain accurate readings.

Washing Instructions

Please follow these instructions to clean your scale:

- 1 Wash the exterior of the scale with a soft, damp cloth.
 - 2 Do not wash scale under running water.
 - 3 Dry with a soft cloth or leave scale to dry on a dish rack with LCD (4) and buttons pointing up.
- ⚠ **DO NOT use liquid bleach or other harsh chemicals.**
 - ⚠ **DO NOT use steel wool or abrasive sponges as this can scratch the surface.**
 - ⚠ **DO NOT submerge the scale.**
 - ⚠ **Avoid pouring liquid directly onto your scale, as liquid may become trapped and may permanently damage internal components.**
 - ⚠ **Water drops on the LCD display will not interfere with the scale's function. These drops will dry and disappear.**

By following these care and washing instructions, your scale will provide you with years of reliable service.



Brewista®
smart brew™
coffee scale with timer
BBCSWT

1133 W. 27th Street
Cheyenne, WY, 82001 USA
N. America: 888-538-8683
Local: 307-222-6086
www.mybrewista.com