



ULTRA SPEC[®] EXT FLAT FINISH N447

Features

- Exceptional film durability.
- Exceptional hiding power.
- Resistant to color fading, blistering, and alkali.
- May be applied at temperatures down to 40°F (4.4°C).
- Easy to apply.
- Rapid dry for quick recoating.
- Provides mildew resistant coating.
- Low VOC in any color.

Recommended For

Recommended for wood, hardboard, vinyl, aluminum and fiber cement sidings; unglazed brick, concrete, stucco, cinder block, and primed metal.

General Description

A professional quality 100% acrylic exterior flat finish which features excellent hiding, film durability and color retention. Fast-dry formula allows for quick re-coating as well as low temperature application.

Limitations

- Do not apply when air and surface temperatures are below 40°F (4.4°C).
- Not for interior use

Product Information

<p>Colors — Standard: White 01 (May be tinted with up to 2.0 fl. oz. of Benjamin Moore[®] Gennex[®] colorants per gallon.)</p>	<table border="1"> <thead> <tr> <th data-bbox="938 787 1323 829">Technical Data</th> <th data-bbox="1323 787 1500 829">Pastel Base</th> </tr> </thead> <tbody> <tr> <td data-bbox="938 829 1323 871">Vehicle Type</td> <td data-bbox="1323 829 1500 871">Proprietary Acrylic</td> </tr> <tr> <td data-bbox="938 871 1323 913">Pigment Type</td> <td data-bbox="1323 871 1500 913">Titanium Dioxide</td> </tr> <tr> <td data-bbox="938 913 1323 955">Volume Solids</td> <td data-bbox="1323 913 1500 955">37.4 ± 2%</td> </tr> <tr> <td data-bbox="938 955 1323 997">Coverage per Gallon at Recommended Film Thickness</td> <td data-bbox="1323 955 1500 997">350 – 450 Sq. Ft.</td> </tr> <tr> <td data-bbox="938 997 1323 1060">Recommended Film Thickness</td> <td data-bbox="1323 997 1500 1060"> <table border="1"> <tr> <td data-bbox="938 997 1323 1039">– Wet</td> <td data-bbox="1323 997 1500 1039">4.0 mils</td> </tr> <tr> <td data-bbox="938 1039 1323 1060">– Dry</td> <td data-bbox="1323 1039 1500 1060">1.5 mils</td> </tr> </table> </td> </tr> <tr> <td colspan="2" data-bbox="938 1060 1500 1144">Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This will ensure color uniformity and minimize the disposal of excess paint.</td> </tr> <tr> <td data-bbox="938 1144 1323 1207">Dry Time @ 77°F (25°C) @ 50% RH</td> <td data-bbox="1323 1144 1500 1207"> <table border="1"> <tr> <td data-bbox="938 1144 1323 1186">– To Touch</td> <td data-bbox="1323 1144 1500 1186">1 Hour</td> </tr> <tr> <td data-bbox="938 1186 1323 1207">– To Recoat</td> <td data-bbox="1323 1186 1500 1207">4 Hours</td> </tr> </table> </td> </tr> <tr> <td colspan="2" data-bbox="938 1207 1500 1291">Painted surfaces can be washed after two weeks. High humidity and cool temperatures will result in longer dry, recoat and service times.</td> </tr> <tr> <td data-bbox="938 1291 1323 1333">Dries By</td> <td data-bbox="1323 1291 1500 1333">Evaporation, Coalescence</td> </tr> <tr> <td data-bbox="938 1333 1323 1375">Viscosity</td> <td data-bbox="1323 1333 1500 1375">103 ± 3 KU</td> </tr> <tr> <td data-bbox="938 1375 1323 1417">Flash Point</td> <td data-bbox="1323 1375 1500 1417">None</td> </tr> <tr> <td data-bbox="938 1417 1323 1459">Gloss / Sheen</td> <td data-bbox="1323 1417 1500 1459">Flat (1-5 @ 85°)</td> </tr> <tr> <td data-bbox="938 1459 1323 1522">Surface Temperature at Application</td> <td data-bbox="1323 1459 1500 1522"> <table border="1"> <tr> <td data-bbox="938 1459 1323 1501">– Min.</td> <td data-bbox="1323 1459 1500 1501">40°F</td> </tr> <tr> <td data-bbox="938 1501 1323 1522">– Max.</td> <td data-bbox="1323 1501 1500 1522">90°F</td> </tr> </table> </td> </tr> <tr> <td data-bbox="938 1522 1323 1564">Thin With</td> <td data-bbox="1323 1522 1500 1564">See Chart</td> </tr> <tr> <td data-bbox="938 1564 1323 1606">Clean Up Thinner</td> <td data-bbox="1323 1564 1500 1606">Clean Water</td> </tr> <tr> <td data-bbox="938 1606 1323 1648">Weight Per Gallon</td> <td data-bbox="1323 1606 1500 1648">11.1 lbs</td> </tr> <tr> <td data-bbox="938 1648 1323 1711">Storage Temperature</td> <td data-bbox="1323 1648 1500 1711"> <table border="1"> <tr> <td data-bbox="938 1648 1323 1690">– Min.</td> <td data-bbox="1323 1648 1500 1690">40°F</td> </tr> <tr> <td data-bbox="938 1690 1323 1711">– Max.</td> <td data-bbox="1323 1690 1500 1711">90°F</td> </tr> </table> </td> </tr> <tr> <td colspan="2" data-bbox="938 1711 1500 1858"> <p align="center">Volatile Organic Compounds (VOC)</p> <p align="center">45 Grams/Liter .37 Lbs./Gallon</p> </td> </tr> </tbody> </table>	Technical Data	Pastel Base	Vehicle Type	Proprietary Acrylic	Pigment Type	Titanium Dioxide	Volume Solids	37.4 ± 2%	Coverage per Gallon at Recommended Film Thickness	350 – 450 Sq. Ft.	Recommended Film Thickness	<table border="1"> <tr> <td data-bbox="938 997 1323 1039">– Wet</td> <td data-bbox="1323 997 1500 1039">4.0 mils</td> </tr> <tr> <td data-bbox="938 1039 1323 1060">– Dry</td> <td data-bbox="1323 1039 1500 1060">1.5 mils</td> </tr> </table>	– Wet	4.0 mils	– Dry	1.5 mils	Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This will ensure color uniformity and minimize the disposal of excess paint.		Dry Time @ 77°F (25°C) @ 50% RH	<table border="1"> <tr> <td data-bbox="938 1144 1323 1186">– To Touch</td> <td data-bbox="1323 1144 1500 1186">1 Hour</td> </tr> <tr> <td data-bbox="938 1186 1323 1207">– To Recoat</td> <td data-bbox="1323 1186 1500 1207">4 Hours</td> </tr> </table>	– To Touch	1 Hour	– To Recoat	4 Hours	Painted surfaces can be washed after two weeks. High humidity and cool temperatures will result in longer dry, recoat and service times.		Dries By	Evaporation, Coalescence	Viscosity	103 ± 3 KU	Flash Point	None	Gloss / Sheen	Flat (1-5 @ 85°)	Surface Temperature at Application	<table border="1"> <tr> <td data-bbox="938 1459 1323 1501">– Min.</td> <td data-bbox="1323 1459 1500 1501">40°F</td> </tr> <tr> <td data-bbox="938 1501 1323 1522">– Max.</td> <td data-bbox="1323 1501 1500 1522">90°F</td> </tr> </table>	– Min.	40°F	– Max.	90°F	Thin With	See Chart	Clean Up Thinner	Clean Water	Weight Per Gallon	11.1 lbs	Storage Temperature	<table border="1"> <tr> <td data-bbox="938 1648 1323 1690">– Min.</td> <td data-bbox="1323 1648 1500 1690">40°F</td> </tr> <tr> <td data-bbox="938 1690 1323 1711">– Max.</td> <td data-bbox="1323 1690 1500 1711">90°F</td> </tr> </table>	– Min.	40°F	– Max.	90°F	<p align="center">Volatile Organic Compounds (VOC)</p> <p align="center">45 Grams/Liter .37 Lbs./Gallon</p>	
Technical Data	Pastel Base																																																						
Vehicle Type	Proprietary Acrylic																																																						
Pigment Type	Titanium Dioxide																																																						
Volume Solids	37.4 ± 2%																																																						
Coverage per Gallon at Recommended Film Thickness	350 – 450 Sq. Ft.																																																						
Recommended Film Thickness	<table border="1"> <tr> <td data-bbox="938 997 1323 1039">– Wet</td> <td data-bbox="1323 997 1500 1039">4.0 mils</td> </tr> <tr> <td data-bbox="938 1039 1323 1060">– Dry</td> <td data-bbox="1323 1039 1500 1060">1.5 mils</td> </tr> </table>	– Wet	4.0 mils	– Dry	1.5 mils																																																		
– Wet	4.0 mils																																																						
– Dry	1.5 mils																																																						
Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This will ensure color uniformity and minimize the disposal of excess paint.																																																							
Dry Time @ 77°F (25°C) @ 50% RH	<table border="1"> <tr> <td data-bbox="938 1144 1323 1186">– To Touch</td> <td data-bbox="1323 1144 1500 1186">1 Hour</td> </tr> <tr> <td data-bbox="938 1186 1323 1207">– To Recoat</td> <td data-bbox="1323 1186 1500 1207">4 Hours</td> </tr> </table>	– To Touch	1 Hour	– To Recoat	4 Hours																																																		
– To Touch	1 Hour																																																						
– To Recoat	4 Hours																																																						
Painted surfaces can be washed after two weeks. High humidity and cool temperatures will result in longer dry, recoat and service times.																																																							
Dries By	Evaporation, Coalescence																																																						
Viscosity	103 ± 3 KU																																																						
Flash Point	None																																																						
Gloss / Sheen	Flat (1-5 @ 85°)																																																						
Surface Temperature at Application	<table border="1"> <tr> <td data-bbox="938 1459 1323 1501">– Min.</td> <td data-bbox="1323 1459 1500 1501">40°F</td> </tr> <tr> <td data-bbox="938 1501 1323 1522">– Max.</td> <td data-bbox="1323 1501 1500 1522">90°F</td> </tr> </table>	– Min.	40°F	– Max.	90°F																																																		
– Min.	40°F																																																						
– Max.	90°F																																																						
Thin With	See Chart																																																						
Clean Up Thinner	Clean Water																																																						
Weight Per Gallon	11.1 lbs																																																						
Storage Temperature	<table border="1"> <tr> <td data-bbox="938 1648 1323 1690">– Min.</td> <td data-bbox="1323 1648 1500 1690">40°F</td> </tr> <tr> <td data-bbox="938 1690 1323 1711">– Max.</td> <td data-bbox="1323 1690 1500 1711">90°F</td> </tr> </table>	– Min.	40°F	– Max.	90°F																																																		
– Min.	40°F																																																						
– Max.	90°F																																																						
<p align="center">Volatile Organic Compounds (VOC)</p> <p align="center">45 Grams/Liter .37 Lbs./Gallon</p>																																																							
<p>— Tint Bases: Bases 1X, 2X, 3X, & 4X Tint bases only with Benjamin Moore[®] Gennex[®] Waterborne colorant.</p>																																																							
<p>— Special Colors: Contact your Benjamin Moore representative</p>																																																							
<p>Certification: VOC compliant in all regulated areas Master Painters Institute MPI # 10 Water vapor permeance (breathability) ASTM D1693: 45.2 perms</p>																																																							
<p>Technical Assistance: Available through your local authorized independent Benjamin Moore retailer. For the location of the retailer nearest you, call 866-708-9180, see www.benjaminmoore.com or consult your local Yellow Pages.</p>																																																							

◇ Reported values are for Pastel Base. Contact Benjamin Moore for values of other bases or colors.

Ultra Spec® EXT Flat Finish N447

Surface Preparation

Surfaces must be clean, dry and free of oil, grease, wax, rust, mildew, chalk and loose or scaling paint. Cement based water proofing paints should be removed. Glossy surfaces must be dulled. Un-weathered areas such as eaves, porch ceilings, overhangs and protected wall areas should be washed with a Benjamin Moore® Clean (N318) and rinsed with a strong stream of water from a garden hose or power washer to remove contaminants that can interfere with proper adhesion. Stains from mildew must be removed by cleaning with Benjamin Moore® Clean (N318) prior to coating the surface. **Caution:** Refer to the (N318) Clean technical data and material safety data sheets for instructions on its proper use and handling.

All new masonry surfaces must be power washed or brushed thoroughly with stiff fiber bristles to remove loose particles. New masonry substrates must be allowed to cure for 30 days before priming or painting. Poured or pre-cast concrete with a very smooth surface should be etched or abraded to promote adhesion, after removing all form release agents and curing compounds.

Difficult Substrates: Benjamin Moore offers a number of specialty primers for use over difficult substrates such as bleeding woods, grease stains, crayon markings, hard glossy surfaces, or other substrates where paint adhesion or stain suppression is a particular problem. Your Benjamin Moore® retailer or Architectural Representative can recommend the right problem-solving primer for your special needs.

WARNING! If you scrape sand or remove old paint, you may release lead dust. **LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE.** Wear a NIOSH-approved respirator to control lead exposure. Carefully clean up with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Primer/ Finish Systems

New surfaces should be fully primed, and previously painted surfaces may be primed or spot primed as necessary. For best hiding results, tint the primer to the approximate shade of the finish coat, especially when a significant color change is desired. **Special Note:** Certain custom colors require a Deep Color Base Primer tinted to a special prescription formula to achieve the desired color. Consult your retailer.

Wood and engineered wood products:

Primer: Ultra Spec® EXT latex Primer (N558), Fresh Start® Multi-Purpose Latex Primer (N023) or Fresh Start® Exterior Wood Primer (094)

Finish: 1 or 2 coats Ultra Spec® EXT Flat Finish (N447)

Bleeding Type Woods, (Redwood and Cedar):

Primer: Fresh Start® Exterior Wood Primer (094) or 1-2 coats of Fresh Start® High-Hiding All Purpose Primer (046) may be used

Finish: 1 or 2 coats Ultra Spec® EXT Flat Finish (N447)

Hardboard Siding, Bare or Factory Primed:

Primer: Ultra Spec® EXT latex Primer (N558)

Finish: 1 or 2 coats Ultra Spec® EXT Flat Finish (N447)

Vinyl & Vinyl Composite Siding

Note: Ensure that the surface is properly cleaned and in good condition. For colors that are safe for use on these substrates, use approved Vinyl Select colors. For more information, see

<http://www.benjaminmoore.com/en-us/for-contractors/painting-vinyl-and-aluminum-siding>

Primer: Fresh Start® Multi-Purpose Latex Primer (N023).

Finish: 1 or 2 coats Ultra Spec® EXT Flat Finish (N447)

Rough or Pitted Masonry:

Primer: Ultra Spec® Masonry Interior/Exterior Hi-Build Block Filler (571)

Finish: 1 or 2 coats Ultra Spec® EXT Flat Finish (N447)

Poured or Pre-cast Concrete and Fiber Cement Siding:

Primer: Ultra Spec® Masonry Interior / Exterior 100% Acrylic Masonry Sealer (608) or Fresh Start® Multi-Purpose Latex Primer (N023)

Finish: 1 or 2 coats Ultra Spec® EXT Flat Finish (N447)

Ferrous Metal (Steel and Iron):

Primer: Ultra Spec® HP Acrylic Metal Primer (HP04) or Super Spec HP® Alky Metal Primer (P06)

Finish: 1 or 2 coats Ultra Spec® EXT Flat Finish (N447)

Non-Ferrous Metal (Galvanized & Aluminum): All new metal surfaces must be thoroughly cleaned with Corotech® Oil & Grease Emulsifier (V600) to remove contaminants. New shiny non-ferrous metal surfaces that will be subject to abrasion should be dulled with very fine sandpaper or a synthetic steel wool pad to promote adhesion

Primer: Ultra Spec® HP Acrylic Metal Primer (HP04)

Finish: 1 or 2 coats Ultra Spec® EXT Flat Finish (N447)

Repaint, All Substrates: Prime bare areas with the primer recommended for the substrate above.

Application

Stir thoroughly before and during use. Apply one or two coats. Paint Application: For best results, use a premium Benjamin Moore® custom-blended nylon/polyester brush, premium Benjamin Moore® roller, or a similar product. Apply paint generously from unpainted area into wet area. This product can also be sprayed.

Conditioning with Benjamin Moore® 518 Extender may be necessary under certain conditions to adjust open time or spray characteristics.		
The chart below is for general guidance		
	Mild conditions	Severe Conditions
	Humid (RH> 50%) with no direct sunlight & with little to no wind	Dry (RH<50%), in direct sunlight, or windy conditions
Brush: Nylon / Polyester	No thinning necessary	Add 518 Extender or water: Max of 8 fl. oz. to a gallon of paint Never add other paints or solvents.
Roller: Premium Quality		
Spray: Airless Pressure: 1500 -2500 psi Tip: .013-.017		

Thinning/Clean up

Clean Up: Clean up with warm soapy water. Spray equipment should be given a final rinse with mineral spirits to prevent rusting.

USE COMPLETELY OR DISPOSE OF PROPERLY. Dry empty containers may be recycled in a can recycling program. **Local disposal requirements vary; consult your sanitation department or state-designated environmental agency on disposal options.**

Environmental, Health & Safety Information

Use only with adequate ventilation. Do not breathe spray mist or sanding dust. Ensure fresh air entry during application and drying. Avoid contact with eyes and prolonged or repeated contact with skin. Wear an appropriate, properly fitted respirator (NIOSH approved) during application, sanding, and clean-up. Follow respirator manufacturer's directions for respirator use. Close container after each use. Wash thoroughly after handling.

WARNING: This product contains a chemical known to the state of California to cause cancer and birth defects, or other reproductive harm.

FIRST AID: In case of eye contact, flush immediately with plenty of water for at least 15 minutes; for skin, wash thoroughly with soap and water. If symptoms persist, seek medical attention. If you experience difficulty breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately.

IN CASE OF SPILL – Absorb with inert material and dispose of as specified under “Clean up”.

**KEEP OUT OF REACH OF CHILDREN
PROTECT FROM FREEZING**

Refer to Safety Data Sheet for additional health and safety information