


For NOVA HD camera, the calibration process for bad pixel is below:


- 1》 Please cover the lens with the lens cap and be sure there is no light leaking into the lens (very important!).
- 2》 Press MENU button and hold it and then press POWER button until the unit comes into FACTORY mode. LCD should show as the following picture:



- 3》 Press the OK button 2 times. The calibration process for bad pixel will start, and it will take about 20 seconds.



- 4》 If the calibration is successful, the LCD will show "OK". If not, please redo steps 1-3.



- 5》 Press POWER button to turn off camera and then press again to turn on.