

- Tip wear will significantly reduce scaler performance as it will alter the ultrasonic frequency.
- The ferrite rod must be tight a loose or broken rod will cause poor or no vibration.
- 3. A correctly functioning tip used on a power setting of 3-4 lights will produce a coolant mist (no dribble) around the tip.

Replacement titanium tips and rods available from iM3 or your iM3 distributor.

www.im3vet.com

