



263BC Indoor Humidity with Temperature

Bios
WEATHER

- A. Indoor Temperature
- B. Indoor Relative Humidity



- 1. Temp Max/Min Button
- 2. Humidity Max/Min Button
- 3. Clear Button
- 4. °C/°F Button



Getting Started:

1. Open the battery cover at the back of the unit.
2. Insert 1 x "AAA" battery in the polarity indicated
3. Close the battery cover

°C/°F Switchable

1. Press the °C/°F button to toggle between Celsius and Fahrenheit.

Maximum and Minimum Temperature

1. Press the TEMP/MAX/MIN button once to display the maximum readings. Press the TEMP/MAX/MIN button again to display the minimum readings.
2. To clear the memory, press the CLEAR button when the max/min temperature is displayed. It will clear the record of the shown field.

Maximum and Minimum Humidity

1. Press the HUMIDITY/MAX/MIN button once to display the maximum readings. Press the HUMIDITY/MAX/MIN button again to display the minimum readings.
2. To clear the memory, press the CLEAR button when the max/min humidity is displayed. It will clear the record of the shown field.

One Year Warranty

If this product proves to be defective in material or workmanship within one year of purchase, please return it to the address below. It will be repaired or replaced without charge upon receipt of the unit prepaid with \$5.00 to cover handling, packaging and return postage. Please include your full name, address, daytime phone number or email address.



16975 Leslie Street
Newmarket, ON L3Y 9A1
www.thermor-ins.com

TH0855_263BC_083007