

# COVER INSTALLATION

SIT ON TOP CRISS-CROSS



SIDE VIEW



SIT ON TOP AND SLIDE DOWN



SLIDE ALL THE WAY



1-SIT THE STRIPES ON TOP

2- SIDE VIEW – LET IT HANG ON THE SIDES

3- SLIDE YOUR COVER DOWN ON TOP OF THE FOAM STRIPES

4- SLIDE DOWN AND FINISH

**DO NOT WRAP THE FOAM AROUND THE PIPE (STEEL BOLLARD)**