

TECHNICAL BULLETIN TECH-01-2020 REV.A

VW 2.0L - 830323-5006S TURBOCHARGER REPLACEMENT

11TH SEPTEMBER 2020





VW 2.0L - 830323-5006S TURBOCHARGER REPLACEMENT

Dear Customer,

Please note, that production of turbocharger 04L 253 014 L / 830323-5006S was stopped.

As a replacement is available turbocharger 04L 253 014 M / 873767-5001S, which <u>is not a</u> <u>direct service replacement</u> for 830323-5006S.

• There is a different position of the flange for EGR pipe on turbine housing – see below



To replace turbocharger 830323-5006S to be ordered following:

- From Garrett Turbocharger 873767-5001S
- From franchised VW dealer
 - EGR pipe
 - Gaskets
 - Heatshield
 - Necessary fasteners






VW 2.0L - 830323-5006S TURBOCHARGER REPLACEMENT

Parts to be ordered from franchised VW dealer

- o EGR pipe
- o Gaskets
- Heatshield
- Necessary fasteners



Please distribute this information to all in your company who may need it.

Best Regards, Arnošt Pátík IAM Senior Technical support Specialist Garrett – Advancing Motion

