


XIT 404's VIDEO PENTAMIRROR AMPHIBICO PHENOM Z1/Z7 MOUNTING INSTRUCTIONS



Thank you for purchasing Xit 404's Video PentaMirror - Amphibico Phenom Z1/Z7 underwater camcorder housing. Below are instructions to help you mount your PentaMirror. On the back are warranty and instructions to help you prolong the life of this product.

Assembly Instructions for Amphibico Phenom Z1/Z7 PentaMirror


1. First you will need to attach the two mounts onto your housing. You will find a left and right mount in your kit.
2. Orient the mounts according to the drawing and attach them with the screws and hex key provided. Be sure to use a corrosion inhibitor such as Lanopro. Available in 1/4-ounce jars from Xit 404 (P/N: LANOJAR1/4).
3. Once the two mounts are secured to your housing attaching the PentaMirror involves sliding the two round pins into the slots of each mount. Next rotate the PentaMirror down until it snaps in place.

Disassembling a PentaMirror

1. The PentaMirror will pull off the mounts by pushing out on the two hooks. Grab the box and pull up until the round pins slid out of the slots.
2. The two mounts remain on your housing.

Replacing Mirrors

1. Inside of the PentaMirror are two hooks that retain the back cover. You need to remove this cover to replace the mirrors.
2. Using a small screwdriver or even your fingernail pry each hook just enough so it pushes out. Be careful to not over bend these hooks. Once the hooks are released pull the cover off.
3. Once the cover is removed the mirrors will drop out.
4. One spare set of mirrors was provided with your kit. Remove the protective plastic cover and slide the new mirrors into the slots in the box. Be sure the mirrored side is towards the inside of the box.
5. Now align the cover with the box and push it in until the hooks snap in place.



XIT 404's VIDEO PENTAMIRROR AMPHIBICO PHENOM Z1/Z7 MAINTENANCE AND WARRANTY

FDM parts - a brief description

Xit 404 manufactures a number of its parts using a process called Fused Deposition Modeling (FDM) This process involves extruding a thread of plastic and laying it down in thin layers to build a part. This enables us to supply you products that enhance your underwater photography and videography.

Care and Maintenance

The FDM part is impact resistant and will withstand most drops from table height. However, as with all plastic parts, they cannot withstand excessive pressure and force without breaking. Being careful means handling the product during assembly with a light touch, do not force.

If your part gets wet let it drip-dry for about an hour. If you have to pack it before it is dry then wrap it in something absorbent such as a paper towel, t-shirt or sock and put it into a plastic bag. This will keep your other parts from getting dripped on.

FDM Plastic Part Warranty

FDM parts are guaranteed to be free of manufacturing defects for a period of one year from date of purchase. Unnecessary force can cause excessive wear and possibly break the parts voiding warranty. Damaged or broken parts will be inspected. If Xit 404 determines that the parts were misused or abused, warranty will be void. Valid purchase receipt is required for all warranty claims.

Care and Maintenance For your PentaMirror - in and out of the water

1. First is to take the necessary precautions while handling your housing with a PentaMirror attached. Since it sits proudly on the top of your housing it is prone to accidental bumps and hits. The PentaMirror was designed to pop off if it gets bumped. Just pop it back on if this happens.
2. Second is cleaning your mirrors. They are plastic and can scratch easily – always use a soft cloth to clean them if needed. While on a dive do not touch the mirrors! If they get silted up or have air bubbles – swish your hand back and forth to push water over them, this will dislodge silt and air bubbles.
3. If they become scratched you may be able to fix them with a scratch remover compound available at most underwater camera dealers. This is the same compound used to polish dome ports. Of course you can always replace them (see instructions on the front page).
4. Once you are done diving and want to pack your PentaMirror, let it drip-dry for about an hour. If you have to pack it before it is dry then wrap it in something absorbent such as a paper towel, t-shirt or sock and put it into a plastic bag. This will keep your other parts from getting dripped on.

Replacement Parts

Product Description	Part Number
Video Mirror, Plastic, 2 x 3.25	PR000100
Aqua Pencil Red Tether	AT0001RD

If you wish to purchase replacement parts or have any questions about your PentaMirror or Viewfinder Plug, please contact your local Xit 404 Dealer.



www.xit404.com