






1.



2.



M5-0.8X10
Flat Head
Machine Screws

3.



3-M6-1.0X20

4.




ø8X40 Plastic Expansion Plug

5.



#12X1-1/4 Flat Head Tapping Screws

6. Front Bracket



7. Back Bracket

