






# GEARS GO

GG-05 BONUS MODEL INSTRUCTIONS


1






2




3





4






5




6




7





8



1x



1x



9




1x


6



1x





1x








10


1



2



11



# BILL OF MATERIALS



4x




2x



3x




1x




2x




4x




2x




1x




1x



1x




2x



1x




6




9

1x


2x




2x



1x



1x



1x