

Femto Flashing Instructions

Step 1 Goto DME Tuning Folder under Software and open femto

Press ZGW Detect

Press Identify

Choose either write tune or write stock

Choose the corresponding file

Wait till flash completes

Goto Step 2 for 8/12 cylinder Motor

Goto Step 3 for 4/6 cylinder Motor

Step 2

Choose DME Secondary

Press Identify

Choose either write tune or write stock

Choose the corresponding file

Wait till flash completes

Step 3

Press clear codes

All done

Remove everything

Turn ignition off

Lock with remote for 15m and make sure the cluster lights are off during this period.

Car won't start until this happens.