

# CM-1027



### Keeping You On High Alert

These strobes provide a bright, flashing indicator for any of our  $CO_2$  or Oxygen Storage Safety Alarms. These 100 cd strobes clearly indicate the alarm level to anyone in the room.

One strobe connects to the sensor display and one to the remote display via an Ethernet cable (included). No additional wiring is required. Strobes flash when Alarm 1, 2 or 3 is triggered. Does not require an additional power source.

#### **Features**

- · Controlled by the RAD unit
- Input voltage: 6 to 12VDC
- · Heavy duty 18-gauge leads
- Clean, Modern Mounting Exterior

#### **Works With**

- RAD-0102-6 | Remote CO, Storage Safety 3 Alarm Remote
- RAD-0012 I Oxygen Enrichment Safety Alarm
- RAD-0002-ZR | Remote Oxygen Deficiency Safety Alarm

#### Accessories

- PRT-1026-R I Red Lens Cap for CM-1027
- PRT-1026-B | Blue Lens Cap for CM-1027
- PRT-1026-C | Clear Lens Cap for CM-1027

### **Specifications**

• 6' ft Ethernet cables (included)



## **TECHNICAL DATA**

## REMOTE CO<sub>2</sub> STORAGE SAFETY 3 ALARM STROBE LIGHTS

## **Electrical and Mechanical Specifications**

Power

Power supplied by RJ45 Ethernet connector (included)







Email Sales@CO2Meter.com | Support@CO2Meter.com

Web CO2Meter.com







