



The club had also entertained a Safety Visit from BSP/TDM Dept.

MPH back door step were highlighted with black & yellow stripes.



Replacement of the pin type bulbs along poolside café walkway

02.04.2019

Continued with the pool planters painting around the poolside kids party areas.



OTHER MAINTENANCE WORKS

IFM BP – SRI came to fixed the lock bracket for the roller shutter at PGC Halfway house canteen.

IFM BP – SRI came and replaced the broken door hinges at Teratai, blocked drainage pipe for the Teratai female toilet wash basin and replaced the damaged door lock/knob at Teratai kitchen door.


Checked & replaced the faulty Admin office sliding door lock.


Main pool was closed for maintenance purposes from 25/03/19.

Poolside café damaged ceiling repair works took place from 31/03/19 as per scheduled.

FOLLOW US

 [officialpanagaclub](#)

 [officialpanagaclubpage](#)

 www.panagaclub.com

SEE YOU ON OUR NEXT MAINTENANCE ISSUE!