

# Two Sided Signs (s)



\*Top down profile of bend pattern on meter & rider

Attachments through key holes on the flange bend (3) per side (6) total

Meter sign \*  (3) #10 x 1.5" pan head screws

Attachments through key holes on the flange bend (2) per side (4) total

Rider sign \*  (2) #10 x 1.5" pan head screws

