TOYOTA LC300/SEQUOIA REAR

10

Dobin

7R

BOLT THROUGH EXISTING HOLES IN CHASSIS

0

MAKE SURE THE END OF THE RESERVOIR HAS CLEARANCE BETWEEN THE NUT AND PIN OF THE SHOCK ABSORBER

N-8 EN853/DIN20022 15N5/16" W.P.215bar(31)7051

00 SERIES LANDCRUISER DIFF BREATHER REAR

PULL BACK

HROUGH

DOWN