
| | | | | | |
|----------------------|--|-------------------------|------------|-------------|---|
| Release Date: | May 1, 2019 | Document Number: | 000-000003 | Rev: | A |
| Title: | SKULLY Release Note (FENIX AR Helmet Firmware) | | | | |

SKULLY FENIX AR Helmet Code v2.1.0

Improvements include:

- Fix for Bluetooth[®] audio playback.
 - Music playing while a voice command was performed would often times not resume. This has been identified and fixed.
- Fix for text-to-speech not working after update to FW (“firmware”) v2.0.9.
 - The text-to-speech module stopped working for some users after updating OTA (“over-the-air”). This has been identified and fixed.

All users should get the “**Update Available**” prompt the next time they start the SKULLY app on their phone and all users will should benefit from this update.

SKULLY FENIX-AR Helmet Code v2.0.9

Improvements include:

- Updated warp map for rear view camera image.
 - The warp map is responsible for manipulating the rear-view camera image to be displayed properly within the HUD. Specific improvements include:
 - Image is flatter.
 - Image is centered.

Email questions to SKULLY Customer Care at:

customercare@skully.com