



printhead cleaner built in your ribbon.

- Built right into your thermal transfer ribbons
- Preventative maintenance
- Fast and easy to use
- Maintains excellent print quality
- Prolongs printhead life
- Minimizes costly downtime



Premium Resin



Super Premium Resin

The ultimate in durability

Benefits


- Maximum durability for harsh environment labeling
- Highest level of resistance to abrasion, heat, steam and various chemicals
- Prints exceptionally on high end films including polyester, vinyl and polyamide

Recommended Stock

- Polyester films
- Vinyl
- Polyamide films

Technical Specifications

Color Code Tab.....	Blue
Maximum Print Speed	6 IPS
Film Thickness.....	4.5 Microns
Total Ribbon Thickness...	6.2 Microns
Transmission Density	1.00
	MacBeth Scale
Ink Melting Point.....	110°C/230°F



What you need to know to quote ribbon business.



Accurate Imaging Resources
Toll Free: 800.700.7377
Phone: 949.888.3880

Thermal Transfer Ribbon Storage Conditions

For optimal print results, thermal transfer printing should occur in the temperature range of 41° F to 95° F at 45% to 85% relative humidity. Suggested storage conditions for up to one year duration are 23° F to 104° F at 20% to 85% relative humidity. Exposing thermal transfer ribbons to direct sunlight or moisture will cause damage to the ribbons.