

U.S. & INTERNATIONAL
PATENTS, TRADEMARKS,
COPYRIGHTS, & REGISTRATIONS
ISSUED & PENDING

**ZOKU, LLC** Hoboken, NJ www.zokuhome.com © 2012 ZOKU, LLC. All Rights Reserved.





The Super Tool should spin easily until it touches the surface of the metal mold.

To prevent the Super Tool from cross threading, keep it **LEVEL AND UPRIGHT** when spinning it on the stick. If the Super Tool is hard to turn or jams **BEFORE** it comes into contact with the mold surface simply unscrew it and try again.

Only apply force when turning the Super Tool once it comes in contact with the top of the mold surface. This will lift the pop from the mold.

